

AN OLD FOUNDATION

- WOOD TIMBER FRAME IN SOUND CONDITION
- PLASTER HAD DEGRADED FROM YEARS OF NEGLECT
- ORIGINAL LATH REQUIRED REPAIR
- ORIGINAL BARREL VAULTS AT SIDE WALLS HAD MINIMAL DAMAGE
- ORIGINAL MEZZANINE FLOOR WAS SLOPED FOR GALLERY SEATING



WITH NEW INTENTIONS

- FLAT CEILING PORTIONS REPAIRED WITH DRYWALL
- ELECTRICITY AND OVERHEAD LIGHTING ADDED
- NEW CROWN MOLDING TRANSITIONS TO RESTORED BARREL VAULTS AT SIDE WALLS
- MEZZANINE STRUCTURE RE-BUILT CREATING ELEVATED DINING AND SMALL GROUP SPACE